

**JEPPESEN**  
**NavData® Alert**

**!! URGENT !!**

**Date:** 26 August 2008

**Subject:** Hiroshima, Japan  
Hiroshima (RJOA)  
VOR Rwy 10 (S10)  
0809

***Approach Transition (HGE) Unusable***

Jeppesen NavData for cycle 0809, effective 28 August 2008, contains incorrect approach transition data for (HGE) approach transition for VOR Rwy 10 (S10) at Hiroshima, Japan (RJOA).

**THEREFORE, DO NOT USE THE APPROACH TRANSITION (HGE) FOR THE VOR RWY 10 (S10) APPROACH PROCEDURE FOR HIROSHIMA AIRPORT (RJOA) IN CYCLE 0809 NAVDATA.**

Revised coding will appear in Jeppesen NavData for cycle 0810, effective 26 September 2008. Until then an entry will appear in the NavData Change Notices beginning 05 September 2008, and this Alert will be posted on the Jeppesen Web site ([www.jeppesen.com](http://www.jeppesen.com), click on Aviation Resources, On-line Publications, NavData NOTAMs/Alerts). Please refer to the Hiroshima, Japan chart dated 22 August 2008 (effective 28 August 2008) for valid information.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445 Fax: 303-328-4122

E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, [www.jeppesen.com](http://www.jeppesen.com). Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.