

**JEPPESEN**
NavData® Alert**!! URGENT !!**

Date: 31 March 2008

Subject: Russell, Manitoba, Canada
Russell Airport (CJW5)
NDB Rwy 35 [N35]
Cycle 0804

Incorrect Missed Approach Point location - Duplicate NDB

Jeppesen NavData for cycle 0804, effective 10 April 2008, contains an incorrect MAPt location on the NDB Rwy 35 [N35] procedure at Russell Airport (CJW5); Russell, Manitoba, Canada. The MAPt identifier ['3Z' NDB] is correct, however an identical identifier ['3Z' NDB] also exist in the same ICAO region with different coordinates. System limitations prevent nav aids with duplicate identifiers from existing within the same region inside avionics equipment. Jeppesen is working with the Canadian authorities to resolve this issue.

IN THE MEANTIME, DO NOT USE THE NDB RWY 35 PROCEDURE [N35] IN CYCLE 0804 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 0805, effective 8 May 2008. Until then an entry will appear in the NavData Change Notices beginning 18 April 2008, and this Alert will be posted on the Jeppesen Web site (www.jeppesen.com, click on Aviation Resources, On-line Publications, NavData NOTAMs/Alerts). Please refer to the Russell, Manitoba (CJW5) 16-1 chart dated 10 April 2008 for valid information.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445 Fax: 303-328-4122

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

cjw5 0804 dup ndb alert